

Oil Field Environmental Incident Summary

Incident: 20140413120856 **Date/Time of Notice:** 04/13/2014 12:08

Responsible Party: WPX ENERGY WILLISTON, LLC

Well Operator: WPX ENERGY WILLISTON, LLC

Well Name: MABEL LEVINGS 14-23HW

Field Name: MANDAREE

Well File #: 26512

Date Incident: 4/13/2014 **Time Incident:** 06:10

Facility ID Number:

County: DUNN

Twp: 149

Rng: 93

Sec: 11

Qtr: SW SW

Location Description:

Submitted By: Jason Rauen

Received By:

Contact Person: Jason Rauen
1801 Burdick Expressway West
Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	45	barrels	45	barrels	45	barrels

Description of Other Released Contaminant:

Flowback water

Inspected:

Written Report Received: 6/9/2014

Clean Up Concluded: 6/1/2014

Risk Evaluation:

There was no immediate risk to human health, fire or explosion as a result of this incident.

Areal Extent:

Potential Environmental Impacts:

No water was impacted or threatened to be impacted. No equipment was damaged and no personal injury occurred as a result of this incident. Impacts were limited to soils on the surface of the constructed well site only.

Action Taken or Planned:

An upstream valve was closed to eliminate the source of the release. Personnel onsite bermed area affected by release to prevent migration on location. A vac truck was immediately dispatched to recover free liquid. Soil conditions will be sampled to evaluate need for soil remediation. Personnel held a safety meeting and discussed importance of routine pre-startup equipment checks, and monitoring of pressures for quick response in unanticipated and emergency situations such as pressure kicks. The subject defusser tank was placed out-of-service and replaced with a tank in proper condition.

Wastes Disposal Location: All recovered waste was disposed of at a permitted and approved facility.

Agencies Involved: BIA, BLM, MHA Energy

Updates

Date: 4/13/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release of unreported amount from a tank overflow remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.